## DEPARTMENT of ENVIRONMENTAL SERVICES Water Division - Watershed Management Bureau

## LAKE TROPHIC DATA

MORPHOMETRIC:							
Lake: BEAR POND Town: CANAAN County: Grafton River Basin: Connecticut Latitude: 43°39'33" N Longitude: 72°04'12" W Elevation (ft): 869 Shore length (m): Watershed area (ha): % watershed ponded:	Areal water load	   d (m/yr): yr <sup>-</sup> ):					
BIOLOGICAL:		June 2000					
DOM. PHYTOPLANKTON (% TOTAL) #1							
#2							
#3							
PHYTOPLANKTON ABUNDANCE (units/mL)							
CHLOROPHYLL-A (µg/L)							
DOM. ZOOPLANKTON (% TOTAL) #1							
#2							
#3							
ROTIFERS/LITER							
MICROCRUSTACEA/LITER							
ZOOPLANKTON ABUNDANCE (#/L)							
VASCULAR PLANT ABUNDANCE							
SECCHI DISK TRANSPARENCY (m)							
BOTTOM DISSOLVED OXYGEN (mg/L)							
BACTERIA (E. coli, #/100 ml) #1							
#2							
#3							
SUMMER THERMAL STRATIFICATION	<u>:</u>						
Depth of thermocline (m): Hypolimnion volume (m³): Anoxic volume (m³) :							

CHEMICAL:					BEAR I			
						J	une 2000	)
DEPTH (m)								
pH (units)								
A.N.C. (Alkalinity)								
NITRATE NITROGEN								
TOTAL KJELDAHL NITROGEN								
TOTAL PHOSPHORUS								
CONDUCTIVITY (µmhos/cm)								
APPARENT COLOR (cpu)								
MAGNESIUM								
CALCIUM								
SODIUM								
POTASSIUM								
CHLORIDE								
SULFATE								
TN : TP								
CALCITE SATURATION INDEX								
All results in mg/L unless indicated otherwise								
TROPHIC CLASSIFICATION:	2000	D.0	).	s.D.	PLANT	СН	L TOTAI	L CLASS
				1			1	T

## **COMMENTS:**

- 1. Bear Pond is considered to be inaccessible to sample.
- We were unable to actually locate the pond. Locals said it did exist but there is no road or path to the pond. Bushwhacking is the only approach and the area is very inhospitable with piles of slash, blow-downs and extremely dense stands of new growth. As one nears the pond the ground becomes very wet and swampy.
- 3. The topographic map depicts an extensive wetland surrounding the pond.